

FILE NOTE

84 Trafalgar Road, Tuross Head

Mick Johnson approached me in May this year regarding the construction of the driveway and the positioning of the stormwater pipe.

I gave him advice re the above and take responsibility for the construction.

I also checked the grades within the driveway, 300mm had to be lowered to achieve a profile that would work.

I also gave consent to modify the plan for the turning area. I thought that the southern side was a more practical position.

I trust that the existing construction can remain with the exception of the pit on the high side of the driveway.

A handwritten signature in black ink, appearing to read 'Peter Lock', written in a cursive style.

Peter Lock
Subdivision Inspector
16 October 2006